



























Part No.	Sapre Parts Name	Picture
6036011	Contra Angle	
6003251	Shell of Handpiece	
6004022	Start Button	
6051122	Motor	
6051123	PCB with upper part of Battery case	
6011055	PCB of Button	
6021016	M1X2 Screw	
6003254	USB Port Protective Cover	
6051132	Damping Ring	
6033083	Button Panel	

6005010	Screw Plug	
6005011	USB Port Cover	
6051107	End Part of Handpiece	
6003259		
6081020	FPC (for connecting Start Button) PS: Need to be soldered to the PCB	
6081021	FPC (for connecting Motor) PS: Need to be soldered to the PCB	
6001009	Shell metal sleeve	
6051075	Charging Base	
6516001	Adapter (EU)	

6516003	Adapter (No Standard)	
6016009	Charging converter (UK standard)	
6016010	Charging converter (Australian standard)	
6016011	Charging converter (US and JP standard)	
6051149	Battery 18500	
6021016	M1X2 Screw	
6021001	ST2.2X6 Screw	
6021002	ST2X4 Screw	